

saltramdata

BUSINESS COMPUTER SYSTEMS • NETWORK SPECIALISTS

Minfos Certified
Hardware Vendor



Motorola

MC3000

Stocktake Problems ?

Problems with your Minfos Stocktake Terminal ?—The MC3090 is the recommended PDA to suit all **Minfos Systems**. However we do get many calls regarding problems and issues, most of which are easily rectified.

Missing Resource assembly: this is generally caused by the wireless connection dropping out. Sometimes a re-boot of the wireless access point is all that is needed. Maybe a better quality Wireless access point would help.

No Laser Scan: It is easy for the operator to closed the Scanner down. Warm Booting the PDA should re-enable this. Either Start, all programs, warm boot..or 7, 9 and Pwr buttons.

No Minfos Program: Generally caused by total loss of power. The PDA needs to be charged initially for 18 hours after which the internal battery will charge. If the Main Battery is remover prior to this the Minfos Program can be lost. Call us for a permanent fix.

Spare Parts: Need a new Battery or lost Stylus ? Call for pricing.

The PDA can also be cold booted but be aware that unless you have the latest firmware and program, Minfos will delete itself. Call us to determine whether you need this upgrade.

minfos® 
Your retail-pharmacy edge

For all enquiries call
1300 307 108
NOW!

saltramdata

BUSINESS COMPUTER SYSTEMS • NETWORK SPECIALISTS

Phone: 1300 307 108

sales@saltram.com.au

www.saltram.com.au